

Holy Rosary Medical Center - Ontario

Catholic Health Initiatives NFP

Malh_hos01A

Building Type	County	
Hospital	Malheur	
Street		
351 SW 9th St		
City	State	Zip
Ontario	OR	97914
Latitude	Longitude	
44.02535	116.97788	
Tracking Code	Inspection Date	
New Building	6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S1	3.6	-2	-0.5	0	1.4	0	-1	0	1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Holy Rosary Medical Center - Ontario

Final RVS Score

Final Type	Final Score
S1	1.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Holy Rosary Medical Center - Ontario

Malh_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2003	2002	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
224160	2	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: U shaped		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries