

Legacy Mt. Hood Medical Center

Legacy Health System

Mult_hos07A

| | | |
|-------------------|-----------------|-------|
| Building Type | County | |
| Hospital | Multnomah | |
| Street | | |
| 24800 SE Stark St | | |
| City | State | Zip |
| Gresham | OR | 97030 |
| Latitude | Longitude | |
| 45.51672 | 122.40696 | |
| Tracking Code | Inspection Date | |
| New Building | 7/5/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S2 | 3.4 | -1.5 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.4 |
| Secondary | C2 | 3.2 | -1 | -0.5 | 0 | 2.4 | 0 | 0 | 0 | 4.1 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Legacy Mt. Hood Medical Center

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| S2 | 1.4 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Legacy Mt. Hood Medical Center

Mult_hos07A

| | | | |
|---|-----------------------------|--|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | 1983 | 1983 | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 97864 | 5 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Steps in Elevation View: Very Irregular Changes | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| Other: Light Cladding | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| E Elevation View | | SE Vertical Irregularity Primary | |
|  | | SE Basement | |
|  | |  | |
| NW Building Name | | W Vertical Irregularity Primary | |
|  | | SW Plan Irregularity Primary | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries