

Rockaway Beach Fire Dept

City of Rockaway Beach

Till_fir08A

Building Type Fire - City	County Tillamook	
Street 270 S Anchor St		
City Rockaway	State OR	Zip 97136
Latitude 45.61012	Longitude 123.9436	
Tracking Code RVS in 2006	Inspection Date 9/6/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Rockaway Beach Fire Dept

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rockaway Beach Fire Dept

Till_fir08A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		Soft Story	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	Primary Structural Type	NE	Plan Irregularity Primary
			
E	Elevation View	E	Elevation View
			
W	Building Name	W	Elevation View
			
SW	Elevation View	SW	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries