


AutoTURN

Using the Program


AutoTURN can be launched from the **Tools** tab of the **ODOT** ribbon workflow in MicroStation or OpenX.

Select the **ODOT** ribbon workflow and then look in the **Add-Ins** group. After you launch the program, you may change back to the Drawing ribbon workflow.



Signing In

When you launch the program, you will need to sign into Transoft. You will see the Transoft Solution pop-up dialog (which you should not close) directing you to the browser. Sign in using your ODOT email address and click NEXT. Enter any additional Microsoft security prompts. You will then see a “Login successful” message and you can then close the windows.



If you don't have an account, you will see “The user was not found” when signing in as shown. Contact EAST at odot.east@odot.oregon.gov to request a free account to use AutoTURN and GuideSIGN.

Transoft Data

Personal AutoTURN files are locally in the **My Transoft Content** folder in the **Desktop\Engineering** folder. The My Transoft Content folder is backed up to F:\ODOT_DATA\Transoft\Backups. You can restore these files yourself, if needed. Because the F: drive is on a server and backed up, even older files can be restored by the Computer Support Desk.