

Accredited Training Providers

Program Name Accredited RRP NW

Address 365 Salem Heights Ave S

City State Zip Salem OR 97302

Phone 503-871-9754

Web www.accreditedrrpnw.com

Lead-Based Paint Activities Courses
--

Risk Assesor Initial:	No
Risk Assesor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial:	Yes
Renovator - Refresher:	Yes
Dust Sampling Tech - Initial:	No
Dust Sampling Tech - Refresher:	No

Program Name American Contractors Organization

Address 11000 SW Barbur Blvd, Ste 100

City State Zip Portland OR 97219

Phone 971-645-4292

Web www.contractorsorganization.org

Lead-Based Paint Activities Courses
--

Risk Assesor Initial:	No
Risk Assesor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial (English/Spanish):	Yes
Renovator - Refresher (English/Spanish):	Yes
Dust Sampling Tech - Initial:	No
Dust Sampling Tech - Refresher:	No

Program Name Crosswall Training/LeadClasses.com

Address 10350 N Vancouver Way #1021

City State Zip Portland OR 97217

Phone 888-840-8388

Web www.leadclasses.com

Lead-Based Paint Activities Courses
--

Risk Assesor Initial:	No
Risk Assesor Refresher:	No
Inspector - Initial:	No
Inspector - Refresher:	No
Supervisor - Initial:	No
Supervisor - Refresher:	No
Project Designer - Initial:	No
Project Designer - Refresher:	No
Abatement Worker - Initial:	No
Abatement Worker - Refresher:	No

RRP Courses

Renovator - Initial:	Yes
Renovator - Refresher:	Yes
Dust Sampling Tech - Initial:	No
Dust Sampling Tech - Refresher:	No

Program Name	EnviroEd, LLC			Lead-Based Paint Activities Courses	
Address	1066 Oldstone Road			Risk Assesor Initial:	No
City State Zip	Allentown	PA	18103	Risk Assesor Refresher:	No
Phone	888-779-8404			Inspector - Initial:	No
Web	www.enviroed.net			Inspector - Refresher:	No
RRP Courses				Supervisor - Initial:	No
Renovator - Initial (Spanish Only):	No			Supervisor - Refresher:	No
Renovator - Refresher:	No			Project Designer - Initial:	No
Dust Sampling Tech - Initial:	No			Project Designer - Refresher:	No
Dust Sampling Tech - Refresher:	No			Abatement Worker - Initial:	No
				Abatement Worker - Refresher:	No

Program Name	Environmental Testing and Training Northwest			Lead-Based Paint Activities Courses	
Address	2345 McGilchrist St SE #5			Risk Assesor Initial:	No
City State Zip	Salem	OR	97302	Risk Assesor Refresher:	Yes
Phone	971-303-8378			Inspector - Initial:	Yes
Web	www.ettnw.com			Inspector - Refresher:	Yes
RRP Courses				Supervisor - Initial:	Yes
Renovator - Initial:	Yes			Supervisor - Refresher:	Yes
Renovator - Refresher:	Yes			Project Designer - Initial:	No
Dust Sampling Tech - Initial:	No			Project Designer - Refresher:	No
Dust Sampling Tech - Refresher:	No			Abatement Worker - Initial:	Yes
				Abatement Worker - Refresher:	Yes

Program Name	Industrial Hygiene Resources			Lead-Based Paint Activities Courses	
Address	8312 West Northview St, Ste 100			Risk Assesor Initial:	No
City State Zip	Boise	ID	83704	Risk Assesor Refresher:	No
Phone	208-323-8287			Inspector - Initial:	No
Web	www.industrialhygieneresources.com			Inspector - Refresher:	No
RRP Courses				Supervisor - Initial:	No
Renovator - Initial:	Yes			Supervisor - Refresher:	No
Renovator - Refresher:	No			Project Designer - Initial:	No
Dust Sampling Tech - Initial:	No			Project Designer - Refresher:	No
Dust Sampling Tech - Refresher:	No			Abatement Worker - Initial:	No
				Abatement Worker - Refresher:	No

Program Name Kachina Contractor Solutions

Address 530 Stahr Rd

City State Zip Elkins Park PA 19027

Phone 888-800-5224

Web www.kachinaleadpaintsolutions.com

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: No

Risk Assesor Refresher: No

Inspector - Initial: No

Inspector - Refresher: No

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial: Yes

Renovator - Refresher: No

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No

Program Name Licencias de Negocios

Address 19144 Molalla Ave.

City State Zip Oregon City OR 97045

Phone 503-925-5323

Web https://licenciasdenegocios.com/

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: No

Risk Assesor Refresher: No

Inspector - Initial: No

Inspector - Refresher: No

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial (English/Spanish): Yes

Renovator - Refresher (English/Spanish): Yes

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No

Program Name Oregon / SW Washington Painters, Drywall Finishers & Allied Trades Apprenticeship

Address 13521 NE Whitaker Way

City State Zip Portland OR 97230

Phone 503-287-4856

Web www.paintertraining.org

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: No

Risk Assesor Refresher: No

Inspector - Initial: No

Inspector - Refresher: No

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial: Yes

Renovator - Refresher: Yes

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No

Program Name Oregon Home Builders Association

Address 2075 Madrona St. Ste 150 SE

City State Zip Salem OR 97302

Phone 503-378-9066 ext 6

Web www.oregonhba.com

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: No

Risk Assesor Refresher: No

Inspector - Initial: No

Inspector - Refresher: No

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial: Yes

Renovator - Refresher: Yes

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No

Program Name PBS Engineering and Environmental Inc

Address 4412 SW Corbett Ave

City State Zip Portland OR 97239

Phone 503-248-1939

Web www.pbsenv.com/service/training

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: Yes

Risk Assesor Refresher: Yes

Inspector - Initial: Yes

Inspector - Refresher: Yes

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial: No

Renovator - Refresher: No

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No

Program Name Safety Directions LLC

Address 1528 Tamera Drive

City State Zip Klamath Falls OR 97603

Phone 541-205-3103

Web www.safety-directions.com

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: No

Risk Assesor Refresher: No

Inspector - Initial: No

Inspector - Refresher: No

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial: Yes

Renovator - Refresher: No

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No

Program Name Tongue Point Job Corps Center

Address 37573 Old Hwy 30

City State Zip Astoria OR 97103

Phone 503-338-5006

Web tonguepoint.jobscorps.gov

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: No

Risk Assesor Refresher: No

Inspector - Initial: No

Inspector - Refresher: No

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial: Yes

Renovator - Refresher: No

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No

Program Name Zack Academy, Inc

Address 2810 E Oakland Park Blvd, #200

City State Zip Ft. Lauderdale FL 33306

Phone 646-564-3546

Web www.zackacademy.com

Lead-Based Paint Activities Courses
--

Risk Assesor Initial: No

Risk Assesor Refresher: No

Inspector - Initial: No

Inspector - Refresher: No

Supervisor - Initial: No

Supervisor - Refresher: No

Project Designer - Initial: No

Project Designer - Refresher: No

Abatement Worker - Initial: No

Abatement Worker - Refresher: No

RRP Courses

Renovator - Initial: Yes

Renovator - Refresher: No

Dust Sampling Tech - Initial: No

Dust Sampling Tech - Refresher: No