## 2014 OMSC Errata August 2015



# Errata for the 2014 Oregon Mechanical Specialty Code

Strikethrough text represents deleted language.
Underlined text represents added language.

### **Errata Summary:**

Section 304.11

#### **Chapter 3 General Requirements**

**304.11 Guards.** Guards shall be provided where appliances, equipment, fans or other components that require service are located within 10 feet (3048 mm) of a roof edge or open side of a walking surface and such edge or open side is located more than 30 inches (762 mm) above the floor, roof or grade below. The guard shall extend not less than 30 inches (762 mm) beyond each end of such appliances, equipment, fans, components and the top of the guard shall be located not less than 42 inches (1067 mm) above the elevated surface adjacent to the guard. The guard shall be constructed so as to prevent the passage of a 21-inch-diameter (533 mm) sphere and shall comply with the loading requirements for guards specified in the Building Code.

**Exception:** This section shall not apply to the replacement, repair or maintenance of an existing appliance or piece of equipment lawfully in existence at the time of the adoption of this code.

#### Contact

Mark Heizer, P.E. Mechanical Code Specialist 503-373-0205 Mark.R.Heizer@oregon.gov

