



1-A-HW-1.30-0.080  
 1-B-CEN-1.75-0.380  
 1-C-FW-3.0-0.260

2-3.5-HW-0.010  
 2A-1.90-FW-0.230

608-508-ENS  
 1-6-0.20  
 6-2-0.320

CHUTE 11  
 93-48  
 18-92  
 16-90  
 12-88  
 CHUTE 12  
 54-16  
 57-24  
 55-24  
 14-60  
 14-58  
 18-56  
 16-54  
 53-18  
 16-52  
 51-30  
 16-50

0.245-14-60 + 54-16 = 0.230  
 0.110-14-58 + 57-24 = 0.330  
 0.180-18-56 + 55-24 = 0.050  
 0.510-16-54 + 53-18 = 0.450  
 0.850-16-52 + 51-30 = 0.835  
 0.240-16-50  
 0.110-18-48 + 47-20 = 0.470  
 0.370-32-46 + 45-20 = 0.350  
 0.050-16-44 + 43-24 = 0.530  
 0.620-35-42 + 41-24 = 0.470  
 0.370-36-46 + 39-24 = 0.100  
 0.375-24-38 + 37-20 = 0.050  
 0.060-24-36 + 35-24 = 0.015  
 0.125-30-32 + 29-24 = 0.100  
 0.940-24-30 + 23-24 = 0.910  
 0.010-20-26 + 25-18 = 0.080  
 0.010-18-24 + 23-30 = 0.150  
 0.040-30-22 + 21-24 = 0.120  
 0.005-30-20 + 19-24 = 0.050  
 0.005-30-18 + 17-30 = 0.010  
 0.005-24-16 + 15-30 = 0.015  
 0.005-24-14 + 13-30 = 0.330  
 0.005-30-12 + 11-30 = 0.160  
 0.005-30-10 + 9-24 = 0.020  
 0.005-30-8 + 7-24 = 0.030  
 0.005-30-6 + 5-30 = 0.460  
 0.010-30-4 + 3-30 = 0.370  
 0.015-24-4 + 3-30 = 0.140  
 0.250-30-2 + 1-30

SCALE  
 40' = 1"  
 22 OCT 1939

NORTH POLE  
 ADIT No. 1  
 SAMPLES BY  
 GEO. B. GUILLOTTE  
 M.T.C. JR.

-20-86 + 85-20  
 -12-84 + 83-24  
 -12-82 + 81-22  
 FACE 6/15/39

North Pole Mine  
 No. 1 Adit Plan

CHUTE  
 CHUTE  
 CHUTE