

MISCELLANEOUS NOTICES AND REPORTS ON WELLS AND STRATIGRAPHIC HOLES
(Submit in triplicate)

This is a combined form, use only portions pertinent to your needs.

OCT 26 1977
DEPT. OF GEOLOGY

To comply with rules and regulations adopted pursuant to ORS 520 (Chapter 667 OL 1953).

Notices		Reports	
Indicate nature of notice by checking below:		Indicate nature of report by checking below:	
Notice of intention to plug well	X	Report on plugging well (use form 5)	
Notice of intention to make formation test		Report on making formation test	
Notice of intention to make production test		Report on making production test	
Notice of intention to abandon well		Report on abandoning well	
Notice of intention to test casing shut-off		Report on testing casing shut-off	
Notice of intention to redrill or deepen well		Report on redrilling or deepening well	
Notice of intention to shoot or chemically treat well		Report on shooting or chemically treating well	
Notice of intention to complete well		Report on completion of well	

Submit notices in triplicate before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Department or agent, of the plan submitted.

Submit reports in triplicate within 20 days after the work specified is completed.

Calif.
Bakersfield, ~~Oregon~~, October 20 1977

Department of Geology and Mineral Industries
Portland, Oregon

Following is a ~~copy of the work log and necessary comments~~ notice of intention to do certain work as described below at the Reichhold Energy Corp. Company or Operator
DSC LONGVIEW FIBRE Well No. 1 in SW/4

Lease
of sec. 11, T. 6N, R. 5W, W.B. & M., Columbia field,
Columbia County. The dates of this work were as follows: _____

Notice of intention to do the work was (was not) submitted on form _____ on _____ 19____
and approval of the proposed plan was ~~was not~~ obtained. (Cross out incorrect words.)

The present condition of the well, including complete casing record, is as follows (Use additional sheets as needed):

1. 7" 23# K cemented at 386'.
2. 6 1/4" hole drilled to 3088'.
3. Plugged with cement from 2535' to 2382'.

FOLLOWING IS A COMPLETE DETAILED ACCOUNT OF ~~WORK DONE AND RESULTS OBTAINED~~ PROPOSED WORK
(USE ADDITIONAL SHEETS AS NEEDED)

1. Hang drill pipe at 2380' and pump in 35 sacks of cement. Calculated to fill to 2190' ±.
2. Hang drill pipe at 466' and pump in 40 sacks of cement.
3. Locate top of plug at or above 330'.
4. ~~Can well at surface and suspend operations.~~

Last produced _____ (date) _____ (net oil) _____ (gravity) _____ (cut)
Never produced.

Approved _____ 19____
except as follows:

DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES
By _____
Director

Reichhold Energy Corporation
Company or operator
By [Signature]
Position Engineer
Send communications regarding well to
Name R. L. Beardsley
Address 2340 Taylor Way
Tacoma, Washington 98421