

Flowpipe Samples of Well Cuttings

United Company of Oregon, Fay #1

Sec. 9, T. 24 S., R. 33 E., Harney County, Oregon

Unlabeled sample	35- 40	45- 50	45- 50	40- 45
"Drill Bits"	40- 45	50- 55	50- 55	45- 50
"Drill Bits"	45- 50	55- 60	55- 60	50- 55
500- 510	50- 55	60- 65	65- 70	55- 60
630- 640	55- 60	65- 70	70- 75	60- 65
640- 650	60- 65	70- 75	75- 80	65- 70
800- 810	65- 70	75- 80	80- 85	70- 75
850- 860	75- 80	80- 85	85- 90	75- 80
900- 910	3070-3075	85- 90	90- 95	80- 85
950- 960	3100- 05	90- 95	3495-3500	85- 90
1040-1050	05- 10	3295-3300	3500- 05	90-3695
1250-1260	10- 15	3300- 05	05- 10	3695-3700
1350-1360	15- 20	05- 10	10- 15	3700- 05
1530-1535	20- 25	10- 15	15- 20	05- 10
2915	25- 30	15- 20	3515 sand	10- 15
20	30- 35	20- 25	20- 25	15- 20
25	35- 40	25- 30	25- 30	20- 25
35	40- 45	30- 35	30- 35	25- 30
40	45- 50	35- 40	35- 40	30- 35
45	50- 55	40- 45	40- 45	35- 40
50	55- 60	45- 50	45- 50	40- 45
55	60- 65	50- 55	50- 55	45- 50
60	65- 70	55- 60	55- 60	50- 55
65	70- 75	60- 65	60- 65	60- 65
70	75- 80	65- 70	65- 70	65- 70
75	80- 85	70- 75	70- 75	70- 75
75- 80	85- 90	75- 80	75- 80	75- 80
80- 85	90-3195	80- 85	80- 85	80- 85
85- 90	3195-3200	85- 90	85- 90	85- 90
90-2995	3200- 05	90-3395	90-3595	90-3795
2995-3000	05- 10	3395-3400	3595-3600	3795-3800
3000- 05	10- 15	3400- 05	3600- 05	3800- 05
05- 10	15- 20	05- 10	05- 10	05- 10
10- 15	20- 25	10- 15	10- 15	10- 15
15- 20	25- 30	15- 20	15- 20	15- 20
20- 25	30- 35	20- 25	20- 25	20- 25
25- 30	35-37 bottom	25- 30	3625- 30	25- 30
30- 35	35- 40	30- 35	30- 35	30- 35
	40- 45	35- 40	35- 40	35- 40