

STATE OF OREGON  
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES  
1069 State Office Building Portland 1, Oregon

PLUGGING RECORD

The owner or operator of any oil or gas well or stratigraphic hole shall file this form with the Director of the State of Oregon Department of Geology and Mineral Industries setting forth in detail the method used in plugging such well. The form must be filed within twenty (20) days after plugging for oil and gas wells, or within sixty (60) days for stratigraphic holes.

Rule L of rules and regulations adopted pursuant to ORS 520.095 (1) (13) (Chapter 667 OL 1953)

Operator V. V. Erntson Field Marion area  
Pool \_\_\_\_\_  
County Marion County

ADDRESS ALL CORRESPONDENCE CONCERNING THIS FORM TO:

Street \_\_\_\_\_ City Albany State Oregon

Lease Name Schermacher Well No. 1 Sec. 27 T. 9 S R. 2 W

Date well was plugged January 14 1959.

Was the well filled with mud laden fluid, according to regulations of the Board of the State of Oregon Department of Geology and Mineral Industries? Yes

How was the mud applied? Through drill pipe Were plugs used? No If so, show all shoulders left for casing, depth of each, and size of casing, size and kind of plugs used, and depths placed. Also amount of cement and rock.

Use additional sheets if necessary.

8" casing cemented at 220 feet.

8" hole to 220 feet.

( SEE ATTACHED SHEET )

4-3/4" hole to 2426 feet T.D.

Was notice given, before plugging, ~~to all interested parties based on record~~ Yes.

V. V. Erntson -  
(Operator)

A. M. Ropp  
Superintendent

AFFIDAVIT

State of \_\_\_\_\_

County of \_\_\_\_\_

I, \_\_\_\_\_, being duly sworn, say that I have knowledge of the facts stated herein, that they are true and correct, and that I am authorized to make this report.

Subscribed and sworn to before me this \_\_\_\_\_ day of \_\_\_\_\_ 19 \_\_\_\_\_

Notary public in and for \_\_\_\_\_

My commission expires \_\_\_\_\_.

**Note:**—Since the plugging was witnessed by a representative from this Department no notarizing is necessary.