STATE OF OREGON
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES
DONALD A. HULL, STATE GEOLOGIST

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

CAPE ARAGO QUADRANGLE
OREGON–COOS CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)

Open File Report
O-95-46
Tsunami Hazard Map of the Cape Arago Quadrangle, Coos County, Oregon

Tsunami inundation boundary
upper limit of area expected to be covered by flood water from a tsunami caused by a magnitude 8.8 undersea earthquake

See accompanying text for use of this map, mapping methodology, and acknowledgments.

Mapping by:

George R. Priest, Oregon Department of Geology and Mineral Industries, October-November, 1995.

Mapped, edited, and published by the Geological Survey

Control by USGS and NOS/NOAA

Topography by photogrammetric methods from aerial photographs taken 1969-70. Field checked 1970

Selected hydrographic data compiled from NOS/NOAA Chart 18587 and hydrographic surveys (1922 and 1928)
This information is not intended for navigational purposes

Projection and 10,000-foot grids ticks: Oregon coordinate system, south zone (Lambert conformal conic)
1000-meter Universal Transverse Mercator grid ticks, zone 10, shown in blue. 1927 North American Datum
The difference between 1927 North American Datum and North American Datum of 1983 (NAD 83) for 7.5 minute intersections is given in USGS Bulletin 1875. The NAD 83 is shown by dashed corner ticks

There may be private inholdings within the boundaries of the National or State reservations shown on this map

UTM GRID AND 1970 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET

CONTOUR INTERVAL 40 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929
DEPTH CURVES AND SOUNDINGS IN FEET–DATUM IS MEAN LOWER LOW WATER
SHORELINE SHOWN REPRESENTS THE APPROXIMATE LINE OF MEAN HIGH WATER
THE MEAN RANGE OF TIDE IS APPROXIMATELY 5 FEET

FOR SALE BY U.S. GEOLOGICAL SURVEY
DENVER, COLORADO 80225, OR RESTON, VIRGINIA 22092
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

OREGON
QUADRANGLE LOCATION

Map photoinspected 1973
No major culture or drainage changes observed

ROAD CLASSIFICATION
Primary highway, hard surface
Secondary highway, hard surface
Light-duty road, hard or improved surface
Unimproved road
Interstate Route
U. S. Route
State Route

CAPE ARAGO, OREG.
43124-C4-TF-024

1970
PHOTOINSPECTED 1973
DMA 1170 IV SW-SERIES V892