

Solid lines are surface workings  
 dashed lines are underground

light colored tuffs  
 intrinsic rhyolite  
 — band of red tuffaceous clay  
 perlite  
 ⦿ cinnabar


RHYOLITE PLUG

Plan of workings  
 Strickland Butte mine  
 Crook County Oregon

Vertical laminae

Rock Ledge  
 May be RHYOLITE

Dip of red band in  
 Trench #5 indicates  
 this area



Floor below red band  
 30' clays above assay  
 6' for 80-60' assay  
 Highest 22'

Floor above red band  
 16-17'  
 raised 2' below surface

Floor sample broken tuff assay blank  
 27' clay above red band carries cinnabar  
 Trench #7  
 clay above red band pans

Churn drill hole not 130' deep  
 cut red tuffaceous clay at 30'

Pan sample distributed  
 Cl. in 24" fracture  
 100' diameter cut 24"  
 60' horizontal cut 62"