

DIAGRAM
Showing Dip of Flag Staff
Lode.




DIAGRAM
showing the Double drifts and
working Incline as constructed.
Scale $2\frac{1}{2}$ to an Inch.

PROFILE
OF THE
FLAG STAFF
MINE,
Showing Shafts and Drifts:
situated in Baker County
Oregon.
June 16th 1896.
C.M. Foster, Surveyor,
for U.S. Mineral Lands.
Scale 50 Feet to an Inch.