	puoding should be summarize	d on the form giving inclusive	pudded or workover operations dates only.	are states.			
		County, pansh or perough	·	State			
istrict		Columbia		OR			
Western		Lease or Unit			Well no.		
Mist			Longview Fibre		41-35-65		
ūth. or W.O. no API #009-00182		Plug & Abandon					
ection 35, Townsh	iip 6 North, Ran	ge 5 West	(Property	Code M830016F1)			
RCO OIL AND GAS O	COMPANY	la		100%	wn		
udded or W.O. begun		Date 11/4/90	Hour	Shut	_		
te and depth of 8:00 a.m.	Complete record for each day		<u> </u>				
11/04/90 (1) TD: 1585'	5-1/2"@ 1570' PREP T/P&A, SNFN MIRU. ACCEPT RIG 1230 HRS. SITP/SICP 275 PSI. RU & BLOW DOWN WELL. PUMP 58.6 BBL LEASE WATER W/NO RTNS. SD PUMP & CHK FOR FLOW. WELL DEAD. SET BPSV, ND TREE, NU BOPE. FUNCTION TEST BOPE, OK. RIH W/TBG T/CHK PBD. TBG STOPS @1312', PBD REPORTED AS 1433'. LAST 2 JTS OF TBG RIH ACTED LIKE GOING THRU TRASH OR FILL. CIRC DN TBG, TBG NOT PLUGGED. MEASURE OUT. TBG TAIL MEASURED AT 1194', PROGNOSIS SHOWS 1196'. TIH T/1298', NO PROBLEMS. CONTINUE IN TO 1361', TBG STOPS AT 1361'. CIRC DN TBG, OK, NOT PLUGGED. POOH W/40,000 LBS OVER-PULL T/1298'. PULL T/1235' W/NO PROBLEM. TIH T/1298'. SECURE WELL. SDFN.						
11/05/90 (2)	5-1/2"@ 1570' WELL P&A'D, RIG RELEASED OPEN WELL, CHK F/FLOW. WELL DEAD. RU HALLIB, MIX & PUMP 58 SX 'G'+3% CACL+0.5 LB/SX FLO SEAL LCM. RATE 2 BPM, PRESS 900 PSI BALANCE PLUG. CIP 0730 HRS. GOT RINS AFTER PMPING 7 BBLS CMT. POOH LD 16 JTS TBG. WOC 3 HRS. RIH T/TAG TOP OF CMT. THEOR TOP 798'. RIH T/976' W/O TAGGING CMT. REVERSE OUT GREEN CMT. CIRC CLEAN. RU HALLIB PUMP 112 SX 'G'+3% CACL IN 2 STAGES. RATE 4 BPM, PRESS 300 PSI. CMT T/SURF @1115 HRS. RD CMTRS, ND BOPE. CLEAN PIT. RELEASE RIG 1300 HRS. P&A WITNESSED & APPROVED BY DAN WERMIEL, DOGAMI.						
11/10/90 (3)	CUT OFF WELLH	EAD. MIX 10' SU	RFACE PLUG. WELL	PLATE ON STUB.			
		*					
		•					
		lo	True				
he above is correct		Date	Title				
ne above is correct	//-	1/17/91	DISTRICT DRIL	LING ENGINEER			

Instructions: Precare and audit the "Initial Report" on the first Wednesday after a well is spudged on workover operations are started.

Daily work prior to soudding should be summarized on the form giving inclusive dates only.

District WESTERN		COLUMBIA COUNTY		State OREGON			
MIST GAS FIELD		Lease or Unit LONGVIEW FIBRE		Wel ⁻ no. 41-35			
Auth or W O. no R46222 API #: 36-009-00182		DRILL & EVALUATE					
SHL: 635.88' S & 364.09' W OF NE CORNER, SEC 35, T6N, R5W, WB&M, COLUMBIA COUNTY, OREGON							
Operator ARCO OIL AND GA	AS COMPANY			A.R Co's W.I. 1,000000			
Spudded or W.O. begun SPUD		B-16-86	2230 HOURS	Prior status if a W.O			
Data and depth as of 8,000 a.m.	Complete record for each day re-	ported					
1-1/4 8-17,18-86	TD: 445' (415') - Change out Hydri1 rubbers (9-5/8" @ 442') MIRU. Spud at 2230 hrs, 8-16-86. Drill 12-1/4" hole 30' - 445'. Circulate and condition. Wiper trip. POOH. Run 11 jts of 9-5/8" 53.5# L-80 and 36# K-55 casing with shoe at 442', float collar at 398'. Circulate and condition. Pump 10 bbl water ahead of 203 sx Class C + 3% CaCl ₂ + .25% Flocele mixed at 15.9 ppg. Displace with mud. Good circulation with 1 bbl cement returns. Did not bump plug. Floats held. CIP at 1708 hrs, 8-17-86. Cut off 9-5/8". Weld on head. Test to 1500 psi. NU BOP.						
2-1/4 8-19-86	TD: 1001' (556') - Drilling ahead (9-5/8" @ 442') MUD: 10.0 ppg VIS: 40 PV/YP: 10/10 GEL: 6/12 pH: 11.5 WL: 7.2 SOLID: 8 Change hydril rubber. Test blind rams and casing to 1500 psi. Test BOPE to 250 psi and 2000 psi. RIH. Tag TOC 393'. Drill cement and float equipment. Drill 8-1/2" hole 445' - 455'. Circulate and condition. Perform LOT (17.8 ppg without leak off). Drill 455' - 466'. Circulate and condition. Perform LOT (21.2 ppg without leak off). Drill 8-1/2" hole 466' - 700'. Trip for BHA. Drill 700' - 1001'.						
3-1/4 8-20 - 86	TD: 1585' (584') - Logging FDC/CNL/GR (9-5/8" @ 442') MUD: 11 ppg VIS: 37 PV/YP: 14/7 GEL: 0/6 pH: 10.6 WL: 7 SOLID: 15.5 BGG: 175 units TG: 3076 units Drill 8-1/2" hole 1001' - 1101'. Hole packed off. Work pipe and clean up hole. Wiper trip. Drill 1101' - 1306'. Circulate gas cut mud. Weight up 10.1 ppg to 10.5 ppg. Drill 1306' - 1585'. CBU. Wiper trip. Circulate and condition. Weight up 10.5 ppg to 10.9 ppg. Wiper trip. Circulate and condition. Weight up 10.9 ppg to 11.0 ppg. CBU. POOH. Run DIL/BHC/SP, sonic failed. RIH FDC/CNL/GR.						
4-1/4 8-21-86	TD: 1585' (PBD: 1434') - Prepare to cut 5-1/2" casing (5-1/2" @ 1570') Run FDC/CNL/GR from 1585' - 445'. Wiper trip. Run Sonic from 1581' - 445', dipmeter from 1585' - 445', check shots from 1584' - 500'. RIH 8-1/2" bit. Circulate and condition. POOH laying down drill pipe. Run 37 jts of 5-1/2" 17# K-55 casing with shoe at 1570', float collar at 1434'. Circulate and condition mud. Cement as follows: 5 bbl water, 40 bbl Mud Flush at 9.8 ppg, 5 bbl water, 208 sx Class G + 10% salt + 1% Halad-322 mixed at 15.8 ppg, followed by 185 sx Class G + 10% salt + 1% Halad-322 mixed at 16.8 ppg. Displace top plug with 35.5 bbl water. Bump plug with 1200 psi, floats held. CIP at 0326 hrs, 8-21-86. Good circulation with trace returns. Land casing. ND BOPE.						
The above is correct Signature		Date Title					
R. L. THOMAS \ 2000 Thomas \ 9/24/96 DISTRICT DRILLING ENGINEER							
For form preparation and distribution, see Procedures Manual. Section 10, Drilling, Pages 86 and 87.							

Number all daily well history forms consecutively as they are prepared for each well.