


OCS
P-093
GREBE
#1



COUNTY Offshore Oregon
 FIELD or LOCATION St. Lawrence Bank
 WELL OCS P-093 GREBE #1
 COMPANY Union Oil Co. of Calif.
 COMPANY UNION OIL CO. of CALIF.
 TERMINATED
 WELL OCS P-093 GREBE #1
 FIELD STONEWALL BANK
 COUNTY STATE OREGON
 LOCATION LAMBERT, COCHISE COUNTY
 OFFICE (N. H. H. ZONE)
 X: 9 8928E Y: 5271-2
 Sec. Twp. Rge.
 Permanent Datum: M. L. W. Elev. M.D. 195'
 Log Measured From: D.F. (remains) Ft. Above Perm. Datum Elev. K.B. D.F. 3.4'
 Drilling Measured From: D.F. G.L.

Date 8-13-65
 Run No. 1
 Depth-Driller 710'
 Depth-Logger 703'
 Bim. Log Interval 7.03'
 Top Log Interval 2.38'
 Casing-Driller @
 Casing-Logger @
 Bit Size 2 1/4"
 Type Fluid in Hole CLAY

Dens. Visc. 7.5 5.3
 pH Fluid Loss 8 5.0 ml
 Source of Sample P.I.F.
 R_m Meas. Temp. 1.0 @ 65 °F
 R_{mt} Meas. Temp. 0.6 @ 82 °F
 R_{mc} Meas. Temp. 5 @ 82 °F
 Source: R_{mt} R_{mc}
 R_m Meas. Temp. 1.0 @ 82 °F
 R_{mt} Meas. Temp. 0.6 @ 82 °F
 R_{mc} Meas. Temp. 5 @ 82 °F
 Time Since Circ. 2 1/2 @ 82 °F
 Max. Rec. Temp. 82 °F
 Equip. Location 103 SAC
 Recorded By ARNOLD
 Witnessed By BILLMAN


REMARKS Zero Point Corrected for V.P. Log

Date	Sample No.	Type Log	Depth	Scale Changes	Scale Up Hole	Scale Down Hole

Dens. Visc. ml
 Source of Sample
 R_m Meas. Temp. °F
 R_{mt} Meas. Temp. °F
 R_{mc} Meas. Temp. °F
 Source: R_{mt} R_{mc}
 R_m Meas. Temp. °F
 R_{mt} Meas. Temp. °F
 R_{mc} Meas. Temp. °F

C.D.: USED S.O.: 1-1/2
 Equip. Used Cart. No.
 Panel No.
 Sonde No.
 IAP No.
 SBR =

Check one, filling in blanks where applicable:
 Surface determined sonde errors used for ILM and ILD.
 ILM and ILD sonde errors corrected for _____ inch borehole signal at R_m =
 ILM and ILD zeros set in hole at depth of _____ feet.



NOTED - SOLANAS