Oregon Schools Seismic Feedback Form

General information:

1. Date of submittal

9/26/2012

2. County

Multnomah

3. School district or special education district

Portland Public Schools, SD 1J

4. Name and title of person submitting report

Jen Sohm, Project Manager
Facilities and Asset Management

5. Year for reporting - Please submit separate forms for each year of reporting

2012

Specific information:

6. Did the district replace any school structures with new buildings during the reporting year?

Yes ○

No ◉

a. If No please go to question #7

b. If Yes please fill out the following information FOR EACH STRUCTURE that was replaced

i. Name and address of the school where structure was replaced

ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)

iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)

iv. Maximum occupancy of new structure

v. Date the new structure became occupied

i. Name and address of the school where structure was replaced
ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

i. Name and address of the school where structure was replaced
ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

i. Name and address of the school where structure was replaced
ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

7. Did the district modify an existing school building in a manner that may affect the seismic risk category of a school?

Yes ◉

No ○

a. If No you are finished - Please go to the end of the form for submittal instructions

b. If Yes please fill out the following information FOR EACH STRUCTURE that was modified

i. Name and address of the school where structure was modified

Peninsula School
8125 N. Emerald
Portland, Oregon 97217

ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)

Chimney

iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)

Chimney height has been reduced.

iv. Date the structure was re-occupied after modification

The chimney height reduction did not impact occupancy.

c. Optional - submit a copy of the seismic rehabilitation or structural engineering report

Please attach to email when you submit this form.

d. Optional - cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)

i. Name and address of the school where structure was modified
Sunnyside School 3421 SE Salmon Street Portland, OR 97214
ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)
Chimney
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
Chimney height has been reduced.
iv. Date the structure was re-occupied after modification
The chimney height reduction did not impact occupancy.
c. Optional – submit a copy of the seismic rehabilitation or structural engineering report
Please attach to email when you submit this form.
d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)

i. Name and address of the school where structure was modified
Marshall Facility 3905 SE 91st Portland, OR 97226
ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)
Chimney
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
Chimney height has been reduced.
iv. Date the structure was re-occupied after modification
The chimney height reduction did not impact occupancy.
c. Optional – submit a copy of the seismic rehabilitation or structural engineering report
Please attach to email when you submit this form.
d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)

i. Name and address of the school where structure was modified
Duniway School 7700 SE Reed College Place Portland, OR 97202
ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)
Chimney
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
Chimney height has been reduced.
iv. Date the structure was re-occupied after modification
The chimney height reduction did not impact occupancy.
c. Optional – submit a copy of the seismic rehabilitation or structural engineering report
Please attach to email when you submit this form.
d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)
Please submit your completed report to: **seismic.feedback@dogami.state.or.us** **Thank you for your cooperation.**