

Oregon Seismic Status Report - 2016



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.
This report was generated by DOGAMI from submitted data.**

School District/ESD: La Grande 1

County: UNION

Contact Name: Joseph Waite

Contact Email: joseph.waite@lagrandesd.org

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Greenwood Elementary, 2300 N Spruce St. La Grande, OR 97850

Kind of Structure: New Classroom, girls restroom and staff restroom. Removal of brick boiler chimney. New aluminum storefront windows throughout.

Type of Modification: Additions to existing school. Wood framed additions. Approx. 2500 sf additional spaces

Date Re-occupied:

Optional:

Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: