

## Oregon Seismic Status Report - 2017



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** McMinnville 40

County: YAMHILL

Contact Name: Peter Keenan

Contact Email: pkeenan@msd.k12.or.us

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Adams School 1330 N.E. Cows Street McMinnville, OR . 97128

Kind of Structure: Entire Structure

Type of Modification: Structural reinforcement throughout with inground piles at foundation , shotcrete walls , floor strapping and roof reinforcement

Date Re-occupied:

**Optional:**

Engineering Report? No *If yes, attachments are appended to this report.*


Cost of Rehab:

Method of Funding:

SRGP grant

Notes:

## Oregon Seismic Status Report - 2017



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** McMinnville 40

County: WHEELER

Contact Name: Peter Keenan

Contact Email: pkeenan@msd.k12.or.us

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Memorial Elementary School 501 N.W. 14th Street McMinnville , OR. 97128

Kind of Structure: Gymnasium and hallways

Type of Modification: Structural steel beams and bracing

Date Re-occupied:

**Optional:**

Engineering Report? No *If yes, attachments are appended to this report.*


Cost of Rehab:

Method of Funding:

SRGP Grant

Notes:

## Oregon Seismic Status Report - 2017



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** McMinnville 40

County: YAMHILL

Contact Name: Peter Keenan

Contact Email: pkeenan@msd.k12.or.us

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Newby Elementary School 1125 N.W. 2nd Street McMinnville , OR. 97128

Kind of Structure: 1960 , 1971 and 1973 Additions to School including gymnasium , classrooms , hallways and roof

Type of Modification: Structural reinforcement including shearwalls, sheathing , anchors , helical ties and roof framing

Date Re-occupied:

**Optional:**

Engineering Report? No *If yes, attachments are appended to this report.*


Cost of Rehab:

Method of Funding:

SRGP

Notes:

# Oregon Seismic Status Report - 2017



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** McMinnville 40

County: YAMHILL

Contact Name: PETER KEENAN

Contact Email: pkeenan@msd.k12.or.us

**Structures Replaced?** No

Name and Address: 800 NE LAFAYETTE AVE

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Cook District Office, 800 N.E. Lafayette Ave., McMinnville, OR 97128

Kind of Structure: Entire building

Type of Modification: Un reinforced brick exterior walls , interior walls , roof , first floor over basement

Date Re-occupied: 04/17/17

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding: Local school Bond

Notes:

# Oregon Seismic Status Report - 2017



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** McMinnville 40

County: YAMHILL

Contact Name: PETER KEENAN

Contact Email: pkeenan@msd.k12.or.us

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Memorial Elementary School 501 N.W. 14th St. McMinnville, OR 97128

Kind of Structure: Gymnasium walls and roof

Type of Modification: Unreinforced brick walls and roof connections

Date Re-occupied: 09/05/17

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding: Local school bond and SRGP grant

Notes:

## Oregon Seismic Status Report - 2017



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** McMinnville 40

County: YAMHILL

Contact Name: PETER KEENAN

Contact Email: pkeenan@msd.k12.or.us

**Structures Replaced?** No

Name and Address: 800 NE LAFAYETTE AVE

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Newby Elementary School, 1125 NW 2nd St., McMinnville, OR 97128

Kind of Structure: gymnasium , classrooms in pre- 1970 wing of school

Type of Modification: Unreinforced exterior brick walls , roof and interior walls

Date Re-occupied: 09/05/17

**Optional:**

Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding: Local school bond and SRGP grant

Notes: