

# Oregon Seismic Status Report - 2018



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Baker 5J

County: BAKER

Contact Name: Doug W Dalton

Contact Email: doug.dalton@bakersd.org

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Baker High School GYM , 2500 E St , Baker City, OR Brooklyn Elementary , 1350 Washington St. , Baker City, OR

Kind of Structure: Baker High School - Main GYM  
Brooklyn Elementary - Entire building

Type of Modification: See Notes.

Date Re-occupied: 8/21/2018

### **Optional:**

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab: Approximately \$2.7

Method of Funding: Seismic Rehabilitation Grant Program and general fund

Notes: BHS Gym - Roof, posts, cable ties, straps, chimney taken down  
Brooklyn Elementary, Roof, sheer wall improvement, strapping

Submission Date: 08/27/18