Oregon Seismic Status Report - 2018

Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.



School District/ESD:	Harrisburg 7
County:	LINN
Contact Name:	Bryan Starr
Contact Email:	bryan.starr@harrisburg.k12.or.us
Structures Replaced?	No
Name and Address:	865 Lasalle Street
Kind of Structure:	
Type of	
Replacement:	
Max Occupancy:	
Date Occupied:	
Structures Modified?	Voc
Name and Address:	Yes Harrisburg Elementary/Middle School Gym , 201 South 6th Street
	namsburg Elementary/Middle School Gym, 201 South our Street
Kind of Structure:	Gymnasium
Type of Modification:	Structural reinforcement
Date Re-occupied:	11/13/2017
Optional:	
•	16 year attach as onto one and add to this assess
Engineering Report?	No If yes, attachments are appended to this report.
Cost of Rehab:	\$1.5 million
Method of Funding:	Seismic Rehabilitation Grant

Submission Date: 08/08/18

Notes: