

Oregon Seismic Status Report - 2018



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: InterMountain ESD

County: UMATILLA

Contact Name: Heidi Sipe

Contact Email: sipeh@umatillasd.org

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of
Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: 1400 7th Street, Umatilla, OR

Kind of Structure: Removed chimney (previous seismic risk) at middle school, updated entry, replaced all windows.

Type of Modification:

Date Re-occupied: 9/4/2018

Optional:

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: