

## Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Blachly 90

County: LANE

Contact Name: Pat Rufo

Contact Email: prufu@blachly.k12.or.us

**Structures Replaced?** No

Name and Address: 20264 Blachly Grange Road

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Triangle Lake Charter School, 20264 Blachly Grange Road, Blachly OR 97412

Kind of Structure: Gymnasium

Type of Modification: Structural reinforcement

Date Re-occupied: 09/03/19

**Optional:**

Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: