Oregon Seismic Status Report - 2019

School District/ESD: Winston-Dillard 116

Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.



County:	DOUGLAS
Contact Name:	Kevin Miller
Contact Email:	millerk@wdsd.org
Structures Replaced?	Yes
Name and Address:	Lookingglass Elementary, 7421 Lookingglass Rd. Roseburg OR 97471
Kind of Structure:	Lower Building (Gymnasium, Cafeteria, Music classroom).
Type of	Pre-Fabricated Metal
Replacement:	
Max Occupancy:	360
Date Occupied:	01/07/19
Structures Modified?	No
Name and Address:	
Kind of Structure:	
Type of Modification:	
Date Re-occupied:	
Optional:	
Engineering Report?	If yes, attachments are appended to this report.
Cost of Rehab:	
Method of Funding:	
Notes:	

Submission Date: 08/19/19 10:33 AM