

# Baker Middle School

Baker SD 5J

Bake\_sch06A

Building Type School	County Baker	
Street 2090 4th St		
City Baker City	State OR	Zip 97814
Latitude 44.77751	Longitude 117.83488	
Tracking Code RVS in 2006	Inspection Date 8/11/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Baker Middle School

## Final RVS Score

Final Type	Final Score
URM	0.2

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Baker Middle School

Bake\_sch06A

Enrollment 350	Year Built (Field Verified) 1916	Year Built (Alt. Source) 1916	Est. Decade Built 1920
Total Area (square ft) 54000	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	



E Elevation View




S Elevation View



W Elevation View




W Falling Hazard



W Vertical Irregularity Primary



W Primary Structural Type



W Building Name



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Baker Middle School

Baker SD 5J

Bake\_sch06B

Building Type School	County Baker	
Street 2320 Washington Ave		
City Baker City	State OR	Zip 97814
Latitude 44.77675	Longitude 117.83619	
Tracking Code RVS in 2006	Inspection Date 8/11/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Baker Middle School

## Final RVS Score

Final Type	Final Score
URM	0.2

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Baker Middle School

Bake\_sch06B

Enrollment 350	Year Built (Field Verified) 1916	Year Built (Alt. Source) 1916	Est. Decade Built 1910
Total Area (square ft) 54000	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E Field Verified Year Built	NW Elevation View	N Elevation View	
			
SW Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries