

Brooklyn Elementary School

Bake_sch07A

Baker SD 5J

Building Type		County	
School		Baker	
Street			
1350 Washington St			
City	State	Zip	
Baker City	OR	97814	
Latitude		Longitude	
44.77764		117.82131	
Tracking Code		Inspection Date	
RVS in 2006		8/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1

Brooklyn Elementary School

Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
316	1955	1955	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
32812	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
Other: Smokestack	None
None	None
None	None



S Elevation View



E Elevation View



E Elevation View



N Elevation View



W Elevation View



W Falling Hazard