


# Haines Elementary School

Bake\_sch08A

Baker SD 5J

Building Type		County	
School		Baker	
Street			
2090 4th St			
City	State	Zip	
Haines	OR	97814	
Latitude		Longitude	
44.91415		117.93427	
Tracking Code		Inspection Date	
RVS in 2006		8/11/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	0	-0.4	0	0	-0.8	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Haines Elementary School

## Final RVS Score

Final Type

Final Score

URM

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
75		1911	1910
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
17500	2	Yes	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



S Elevation View



E Elevation View

