

Burnt River School

Burnt River SD 30J

Bake_sch09A

Building Type School	County Baker	
Street PO Box 8 Highway 26		
City Unity	State OR	Zip 97884
Latitude 44.43986	Longitude 118.19191	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Burnt River School

Final RVS Score

Final Type
RM1

Final Score
-0.1

FEMA-154 Collapse Potential

Very High (100%)



Burnt River School

Bake_sch09A

Enrollment 76	Year Built (Field Verified) 1968	Year Built (Alt. Source) 1968	Est. Decade Built 1960
Total Area (square ft) 55000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary		E Elevation View	
			
		NW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Burnt River School

Burnt River SD 30J

Bake_sch09B

Building Type School	County Baker	
Street PO Box 8 Highway 26		
City Unity	State OR	Zip 97884
Latitude 44.44039	Longitude 118.19172	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	0	-1.2	0	3.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Burnt River School

Final RVS Score

Final Type	Final Score
W2	3.6

FEMA-154 Collapse Potential

Low (<1%)



Burnt River School

Bake_sch09B

Enrollment 76	Year Built (Field Verified) 1968	Year Built (Alt. Source) 1968	Est. Decade Built 1960
Total Area (square ft) 55000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Burnt River School

Burnt River SD 30J

Bake_sch09C

Building Type School	County Baker	
Street PO Box 8 Highway 26		
City Unity	State OR	Zip 97884
Latitude 44.44035	Longitude 118.19128	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Burnt River School

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Burnt River School

Bake_sch09C

Enrollment 76	Year Built (Field Verified) 1968	Year Built (Alt. Source) 1968	Est. Decade Built 1970
Total Area (square ft) 55000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Torsion: Eccentric Stiffness None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries