

Monroe RFPD

Bent_fir01A

Monroe RFPD

Building Type Fire - RFPD	County Benton	
Street 25483 Bellfountain Rd		
City Monroe	State OR	Zip 97456
Latitude 44.32939	Longitude 123.36027	
Tracking Code RVS in 2006	Inspection Date 6/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Monroe RFPD

Final RVS Score

Final Type	Final Score
S3	2.8

FEMA-154 Collapse Potential

Low (<1%)



Oregon Geology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Primary Structural Type			

