

# Corvallis Locke Fire Station

City of Corvallis

Bent\_fir06A

Building Type	County
Fire - City	Benton
Street	
544 Nw Lewisburg Ave	
City	State Zip
Corvallis	OR 97330
Latitude	Longitude
44.6286	123.25112
Tracking Code	Inspection Date
New Building	9/15/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Corvallis Locke Fire Station

## Final RVS Score

Final Type	Final Score
<input type="text"/>	<input type="text"/>

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Corvallis Locke Fire Station

Bent\_fir06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2001	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
E	General Site	E	General Site
			
E	General Site		