

# Corvallis Fire Station #2

Bent\_fir07A

City of Corvallis

Building Type	County	
Fire - City	Benton	
Street		
500 SW 35th St.		
City	State	Zip
Corvallis	OR	97333
Latitude	Longitude	
44.5623	123.29029	
Tracking Code	Inspection Date	
RVS in 2006	6/27/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	0	0	0	-0.8	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Corvallis Fire Station #2

## Final RVS Score

Final Type	Final Score
W2	1

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Corvallis Fire Station #2

Bent\_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Plan Irregularity Primary			