

Corvallis Fire Station 1

Bent_fir08A

City of Corvallis

| | |
|-----------------|-----------------|
| Building Type | County |
| Fire - City | Benton |
| Street | |
| 400 Nw Harrison | |
| City | State Zip |
| Corvallis | OR 97330 |
| Latitude | Longitude |
| 44.56742 | 123.26117 |
| Tracking Code | Inspection Date |
| New Building | 9/15/2006 |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Corvallis Fire Station 1

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| | |

FEMA-154 Collapse Potential

Low (<1%)

Corvallis Fire Station 1

Bent_fir08A

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | 1994 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |