

Good Samaritan Regional Medical Center - Corvallis

Samaritan Health Services NFP

Bent_hos01A

Building Type	County	
Hospital	Benton	
Street		
3600 Nw Samaritan Dr		
City	State	Zip
Corvallis	OR	97330
Latitude	Longitude	
44.60298	123.25288	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Good Samaritan Regional Medical Center - Corvallis

Final RVS Score

Final Type Final Score

FEMA-154 Collapse Potential

Low (<1%)

Good Samaritan Regional Medical Center - Corvallis

Bent_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1994	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	