

Corvallis Police Department

City of Corvallis

Bent_pol04A

Building Type Police - City	County Benton	
Street 180 NW 5th St		
City Corvallis	State OR	Zip 97330
Latitude 44.56574	Longitude 123.26312	
Tracking Code RVS in 2006	Inspection Date 6/26/2006	



Seismicity Zone: High		Corvallis Police Department								
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0
Final RVS Score		Final Type C2		Final Score 0.7						
FEMA-154 Collapse Potential						High (>10%)				



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Corvallis Police Department

Bent_pol04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		Short Columns	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Primary Structural Type	S	Vertical Irregularity Secondary short column
			
S	General Site	S	Primary Structural Type
			
S	Other	S	General Site