

# Cheldelin Middle School

Corvallis SD 509J

Bent\_sch02A

Building Type	County	
School	Benton	
Street		
987 Conifer Blvd Ne		
City	State	Zip
Corvallis	OR	97330
Latitude	Longitude	
44.60104	123.23732	
Tracking Code	Inspection Date	
Structural Engineering Report		
9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cheldelin Middle School

## Final RVS Score

Final Type	Final Score
RM1	0.7

## FEMA-154 Collapse Potential

High (>10%)

# Cheldelin Middle School

Bent\_sch02A

Enrollment 579	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built
Total Area (square ft) 106699	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	