

Hoover Elementary School

Corvallis SD 509J

Bent_sch04A

Building Type School	County Benton	
Street 3838 Nw Walnut Blvd		
City Corvallis	State OR	Zip 97330
Latitude 44.59263	Longitude 123.29342	
Tracking Code Structural Engineering Report	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)

Hoover Elementary School

Bent_sch04A

Enrollment 411	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built
Total Area (square ft) 40500	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	