

Jefferson Elementary School

Corvallis SD 509J

Bent_sch05A

Building Type		County	
School		Benton	
Street			
1825 Nw 27th St			
City	State	Zip	
Corvallis	OR	97330	
Latitude		Longitude	
44.58581		123.2803	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
319		1960	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
44057	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions