

Mt View Elementary School

Corvallis SD 509J

Bent_sch07A

Building Type	County	
School	Benton	
Street		
340 Ne Granger Ave		
City	State	Zip
Corvallis	OR	97330
Latitude	Longitude	
44.62819	123.23929	
Tracking Code	Inspection Date	
Structural Engineering Report	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Mt View Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
385		1954	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
47393	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions