

Linus Pauling Middle School

Corvallis SD 509J

Bent_sch08A

Building Type	County	
School	Benton	
Street		
1111 NW Cleveland Ave		
City	State	Zip
Corvallis	OR	97330
Latitude	Longitude	
44.58638	123.26402	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Linus Pauling Middle School

Final RVS Score

Final Type	Final Score
<input type="text"/>	<input type="text"/>

FEMA-154 Collapse Potential

Low (<1%)

Linus Pauling Middle School

Bent_sch08A

Enrollment 700	Year Built (Field Verified) 2004	Year Built (Alt. Source) 2004	Est. Decade Built
Total Area (square ft)	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	