

Crescent Valley High School

Corvallis SD 509J

Bent_sch09A

Building Type	County	
School	Benton	
Street		
4444 Nw Highland Dr		
City	State	Zip
Corvallis	OR	97330
Latitude	Longitude	
44.61617	123.26319	
Tracking Code	Inspection Date	
Structural Engineering Report		
9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crescent Valley High School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)

Crescent Valley High School

Bent_sch09A

Enrollment 1045	Year Built (Field Verified) 1970	Year Built (Alt. Source) 1970	Est. Decade Built
Total Area (square ft) 272325	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	