

Monroe Grade School

Monroe SD 1J

Bent_sch10A

Building Type		County	
School		Benton	
Street			
600 Dragon Dr			
City	State	Zip	
Monroe	OR	97456	
Latitude		Longitude	
44.31203		123.29852	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Monroe Grade School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
313		1954	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
31626	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site

