

# Franklin School

Corvallis SD 509J

Bent\_sch11A

Building Type School	County Benton	
Street 750 Nw 18th St		
City Corvallis	State OR	Zip 97330
Latitude 44.57471	Longitude 123.27314	
Tracking Code Structural Engineering Report	Inspection Date 9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Franklin School

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)

# Franklin School

Bent\_sch11A

Enrollment 369	Year Built (Field Verified) 1946	Year Built (Alt. Source) 1946	Est. Decade Built
Total Area (square ft) 35944	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries