

Corvallis High School

Corvallis SD 509J

Bent_sch12A

Building Type	County	
School	Benton	
Street		
1400 Nw Buchanan Ave		
City	State	Zip
Corvallis	OR	97330
Latitude	Longitude	
44.57552	123.2688	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Corvallis High School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1378		2005	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
240095	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions