

# Wilson Elementary School

Corvallis SD 509J

Bent\_sch14A

Building Type	County	
School	Benton	
Street		
2701 Nw Satinwood		
City	State	Zip
Corvallis	OR	97330
Latitude	Longitude	
44.59521	123.25651	
Tracking Code	Inspection Date	
Structural Engineering Report	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

## Final RVS Score

Final Type	Final Score
W2	0.9

## FEMA-154 Collapse Potential

High (>10%)

# Wilson Elementary School

Bent\_sch14A

Enrollment 292	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built
Total Area (square ft) 46344	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries