

Inavale School

Corvallis SD 509J

Bent_sch17A

Building Type	County	
School	Benton	
Street		
30252 Bellfountain Rd		
City	State	Zip
Corvallis	OR	97333
Latitude	Longitude	
44.4598	123.33777	
Tracking Code	Inspection Date	
Structural Engineering Report	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Inavale School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)

Inavale School

Bent_sch17A

Enrollment 181	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built
Total Area (square ft) 16032	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries