

Clemens Primary School

Bent_sch18A

Philomath SD 17J

Building Type		County	
School		Benton	
Street			
535 S 19th St			
City	State	Zip	
Philomath	OR	97370	
Latitude		Longitude	
44.53616		123.35819	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Clemens Primary School

Final RVS Score

Final Type

Final Score

W2

5.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
177		2000	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
82500	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions