

# Fir Grove Primary School

Greater Albany SD 8J

Bent\_sch22A

Building Type		County	
School		Benton	
Street			
5355 NW Scenic Dr			
City	State	Zip	
Albany	OR	97321	
Latitude		Longitude	
44.68931		123.14449	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fir Grove Primary School

## Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
172		1963	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
19796	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions