

Oak Grove Intermediate

Bent_sch23A

Greater Albany SD 8J

Building Type		County	
School		Benton	
Street			
1500 NW Oak Dr			
City	State	Zip	
Albany	OR	97321	
Latitude		Longitude	
44.65735		123.14833	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Intermediate

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
159		1948	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
59681	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions