

# Art Center

Clackamas CC

Clac\_coc01A

Building Type		County	
Community_College		Clackamas	
Street			
19600 S Molalla Ave			
City	State	Zip	
Oregon City	OR	97103	
Latitude	Longitude		
45.32483	122.573		
Tracking Code	Inspection Date		
RVS2006 & FEMA154	9/22/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Art Center

## Final RVS Score

Final Type


Final Score

W2

3.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Art Center

Clac\_coc01A


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1950	1950	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
11648	2	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Elevation View



W Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries