

Building Type Community_College	County Clackamas	
Street 7616 SE Harmony Rd		
City Milwaukie	State OR	Zip 97222
Latitude 45.43233	Longitude 122.5857	
Tracking Code RVS2006 & FEMA154	Inspection Date 9/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Tertiary	RM1	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1

CCC Harmony

Final RVS Score

Final Type	Final Score
W2	-0.1


FEMA-154 Collapse Potential

Very High (100%)

No
Planview
Available



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1901	1901	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
27442	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Other: Brick Veneer		None	
None		None	
			
E Vertical Irregularity Primary		E Primary Structural Type AND CHIMNEY	
		E Primary Structural Type	
			
SE Plan Irregularity Primary AND MORE WOOD		S Plan Irregularity Primary	
		S Secondary Structural Type CONC BOILER RM, FALLING HAZ	
			
SW Falling Hazard		SW Elevation View	
		W Primary Structural Type	





NW Elevation View



N Other
BRICK WALL



NE Elevation View

