

# Family Res. Center

Clackamas CC

Clac\_coc04A

Building Type Community_College	County Clackamas	
Street 19600 S. Molalla Avenue		
City Oregon City	State OR	Zip 97103
Latitude 45.32497	Longitude 122.57717	
Tracking Code RVS2006 & FEMA154	Inspection Date 9/22/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	-2.4	-0.4	0	0	-1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


## Family Res. Center

### Final RVS Score

Final Type	Final Score
W2	-1.5

### FEMA-154 Collapse Potential

Very High (100%)



# Family Res. Center

Clac\_coc04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1992	1992	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
16994	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE General Site Y2K ADDN		W Elevation View	
		NW Vertical Irregularity Primary	
		E Plan Irregularity Primary	
		NE Elevation View	
		SE Plan Irregularity Primary	
		SE Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries